Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE __yes __no

1. Nam	(indicate p	referred name)		
historic ORIC	GINAL FARMHOUSE	OF ABERDEEN HILI	is .	
and/or common	"Thl. Col?	F.::Mhouse"		
2. Loca	ation			
street & number	318 Roberts V	Var		not for publication
city, town ABEI	<u> </u>	vicinity of	congressional district	
state MARYLA	AND	county	HARFORD	
3. Clas	sification			
Category district building(s) _X structure site object	Ownership public private both Public Acquisition in process being considered not applicable	Status _X_ occupied unoccupied work in progress Accessible yes: restricted _X yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names a	nd mailing addresse	s of <u>all</u> owners)
name Capta	in and MrsKei	th and Lilly Fre	nch	
street & number		.v., SW P-12		··:1-206-588-322
city, town TAC			and zip code WASH	
		al Description		• • • • • • • • • • • • • • • • • • • •
courthouse, regis	stry of deeds, etc. BEL	Air COURTHOUS	E	liber <i> 033</i>
street & number		MAIN STREET		folio /096
city, town		ARYLAND 210		10110 / 0 / 0
· · · · · · · · · · · · · · · · · · ·		in Existing		eys
title				
date			federal state	e county loca
ository for su	rvey records			
city, town		•	state	

7.	Description	Survey	No. NA- 137

Condition excellent good fair	deteriorated ruins unexposed	Check one unaltered	Check one original site moved date of move	
tair	unexposed			

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

- 2. Parlor and Dining Room- located on either side of foyer; both rooms have an original slate fireplace with engraved designs beneath the slate mantel. A dish-warming closet exists in the side wall above the dining room fireplace.
- 3. Large country kitchen contains a hidden closet (via trapdoor entrance) with original acorn/heart cloak hooks still attached.
- 4. Servants Stairway leads from kitchen to servant's bedchamber just above the kitchen.
- 5. Summer kitchen contains original columns(unrestored) and windows(unrestored) with hidden doorway to pantry; both adjoin main kitchen.
- 6. Basement contains root cellar.
- C. Interior 2nd and 3rd Levels
 - 1. Original Fireplace and mantel still exists in small bedroom; closed off heat vent still existing for reinsertion of grate.
 - 2. Double finished attic, plus 3rd trap-door attic. Original hardwood floor, and traces of bordered wall paper still exist; original windows open from middle and outward toward the floor.
 - 3. 3rd attic- entrance through main attic; construction design most visible here: mitered rafters and cut nails, exposure of framework with cut boards done by circular saw (see Jim Wollon's letter 6/8/82).

8. \$	Sign	ificance		Survey No.	14-1739
1600	0–1499 0–1599 0–1699 0–1799 0–1899	Areas of Significance—Cl — archeology-prehistoric — archeology-historic — agriculture _X architecture — art — commerce — communications		law literature military music	science sculpture social/ humanitarian theater
Specific	dates		Builder/Architect		
check:	ar Appl	icable Criteria:A nd/or icable Exception:A l of Significance:	BCD		
support	-	a summary paragraph c		a general statemen	t of history and
Histon	rical	Significance Cont	inued-		

8. Significance

- Acorn/Heart Cloak Hooks-symbols of strength and love; incidently, a large oak tree still grows in the back yard.
- Fireplaces the more ornately designed fireplace is located in the parlor, the most important room for receiving guests, and a place for evening family get togethers.

 Ceremic/porcelain door knobs- color reveals social philosophy

NA-1729

- of "putting one's best foot forward". Ground level rooms have white showy knobs; upper level rooms have less attractive brown knobs.
- Age- excludes 2 side additions built on by Lorraine Jackson's father; II. according to Ms. Jackson.
 - Title Search Α.
 - Geneology tracing of James Cole dates of birth and death; to coincide with James Cole tombstone in "Abandoned Roberts Way Cemetery" listed in Mark Edwards' surveyed sites. letter of 3/23/82 Lumber Construction in 3rd floor 3rd attic of 310 Roberts Way.

 - Architecture D_{\bullet}

III.. Conclusion

The house is presently surrounded by a community of well kept homes comprised of retired members who are equally proud of the significance of "the original farmhouse". It remains more valuable than any two dimensional portrait or picture of Victorian architecture. It is truly a living testimony of an era in history, dating back over 100 years ago that brings the past to our present day door step.

Major Bibliographical References

Survey No. NA-1729

"HISTORY OF ABERDEEN" by Michard F. Crenin, publ. by Bicentennial Comm. of Aberdeen, 1976 - (stery of 118 Roberts Way begins with Swan House, Paradise Rd., Pg. 9) "OUR HARFORD HERITAGE" by C. Milton Wright, publ. French Bay Frinting Co., 1980. "HARFORD COUNTY HISTORICAL SOCT TY BULLETIN" No. 1 8 Spring Edition 1983

Geographical Data

Acreage of nominated property ene-tenth	of an Acre	
Quadrangle name		Quadrangle scale
UTM References do NOT complete UTM ref	erences	
Zone Easting Northing	B	asting Northing
c	D L	
E	F L	
G	н 🔟 📙	
Verbal boundary description and justification	1	
List all states and counties for properties ov	erlapping state or cou	nty boundaries
state code	county	code
state code_	county	code
11. Form Prepared By		
name/title Mrs. Lilly French; 3/28	183 Mrs. G	Jan Novotry 3-31-83
organization	date	July 12, 1983
street & number 1424 Nabash Dr.	ive. telep	phone 301-676-6169
city or town Bel air, Maryla	xA state	2/014

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House

21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

7. Description Survey No. HA-1739

Condition Excellent Good fair	deteriorated ruins unexposed	Check one unaltered _X_ altered	Check one _X_ original s moved	site date of move	

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

This is a three-story Victorian home, believed to be the original farmhouse of Aberdeen Hills at an age of over 100+ years. The following gives a description with supportive resources of our home:

Description:

- I. Architectural Style Victorian
 - A. See xeroxed copy of similarly styled Victorian house, taken from The Victorian Home In America by John Maass, copy. 1972.
 - B. See glossy photographs and slides of 318 Roberts Way; compare this original structural design with xeroxed copy mentioned above.
- II. Specific Designs of 318 Roberts Way- original house rests on the original stone foundation.
 - A. Exterior Front
 - 1. Arched upper window in center of pitched roof.
 - 2. Original chimney is a chimney within a chimney; second original chimney to the right of the house no longer exists.
 - 3. Front Porch (8'x34')
 - a. Note restored column mouldings, and hanging decor from beneath the roof.
 - b. Note the position of front porch facing the east; allows for cool relaxation after a hot summer day of farm work.
 - 4. Entry Way- Front Door
 - Original turn-key door bell recessed in carved right window panel.
 - b. Transom window and two side windows within carved panels frame the original door and doorway.
 - c. Note that double arched shaped carving on door's interior matches arched exterior window at top of pitched roof. Note also an ornate metal rectangular key-hole on interior side of door.

B. Interior - Downstairs

- 1. Entry Way Foyer
 - a. Doors some of the orginal interior doors possess the original mortised locks and porcelain knobs.
 - b. Doorways all framed with original carved panels; windows framed the same.
 - c. Stairway and Banister ornately carved panels line the side of stairway with matching design above the staircase. The end of the stair rail is scroll shaped with a center hole to receive a ruby or other gem, denoting complete ownership of the home when paid in full. The scroll sits atop an original cylindrical post.
 - d. Hardwood floors and stairs throughout original house.
 - e. High ceilings, typical of older homes are about 8 feet high.

Period prei	historic 10–1499 10–1599 10–1699 10–1799 10–1899	Areas of Significance— archeology-prehistoric archeology-historic agriculture X architecture art commerce communications	community planning conservation economics deducation engineering exploration/settlement	landscape architectu law literature military	science Scuipture X social/ humanitarian theater transportation
Specific	dates		Builder/Architect		other (specify
check:	and	I/OF	B C D		
	Applic	able Exception:	A _B _C _D _E	F G	
	7 1		national _state		

Prepare both a summary paragraph of significance and a general statement of history and support. The following facts of this unique home should merit both preservation and restoration support: This Victorian home of 100+ years (see 1799 Hauducoeur map of Chesapeake Bay area) is still in good condition externally and internally; offers original architectural examples as such. It has been cited as being the original farmhouse of Aberdeen Hills. original barn was torn down about the time new area homes were being constructed. (See eyewitness neighbor, Mary Hoffman at 321 Roberts Way. She remembers the barn's approximate location; also, see Lorraine Jackson, local Havre de Grace realtor (939-0607) who lived in the farmhouse while her contractor father built up the farmland with local homes).

The original owner being a Mr. James Cole. (I was personally introduced an elderly lady, a decendant of Mr. Cole's who said that she remembers great-great uncle Cole building the house when she was a little girl; she remembers him speaking of Pres. Abraham Lincoln). Possible tangible reference to the Cole geneology can be obtained from local Aberdeen lawyer, a Mr. J. Harlan Livezey who once told me that he has photograph records of the Abandoned Roberts Way Cemetery. (See lawyer referral list) He has a hobby of doing geneology research. Finally, Mr. James Cole's tombstone(undated) lies in the Abandoned Roberts Way Cemetery, just 4 house lots down from the farmhouse. (see map plus letter of Mark Edwards, 3/23/82).

The agricultural history of Aberdeen began and existed in this very location where farming land once flourished within the vicinity of the farmhouse. More recently, (June, 1980) my husband and I were awarded the Aberdeen Appearance and Preservation Award for the many efforts taken to restore the home. (See xeroxed copy of award enclosed). Subsequently, I have also pursued local and state information leading to this home's listing for the historical registers.

Historical Significance -

I. Architecture

- A. Exterior well preserved example of Victorian Architecture B. Interior Decor
- - Detailed molding outlining windows and doors; carved panels on doors and doorway; carved designs lining stairway; chair railing attached to dining room walls; hardwood floors throughout; all revealing quality and "pride of ownership" indicative of our forefathers.








HA-1746 /739 COLE FARMHOUSE

Photographer: Kevin Allen





IMPACT IMAGES
BY KEVIN ALLEN
Wedding - Portrait & Sports
(301) 836-8242















HA-1746 /739 COLE FARMHOUSE

Photographer: Kevin Allen

IMPACT IMAGES
BY KEVIN ALLEN
Wedding - Pertrait & Sports
(301) 836-8242